Inbound Shipments

(1)

Field Activity
Shipment on
DD Form 1348
(SHP, Doc ID)

DLA shipments: No DSS transactions for shipment/receipt of assets between blocks (1), (2), (3), and (4).

(3)

Orange Park Warehouse
(off base)
DoDAAC: N39824
Inventory/Storage
Maintained in
Desktop computer
Excel Spreadsheets

NADEP transport's asset's

(4)

A/F - ALC
DLA
Shipment on
DD Form 1348
(A2, A5 Doc ID)

(2)

DLA
NAS JAX
Bldg 110,
Door 16
(no DSS acceptance/receipt transactions)

NADEP transport's asset's

NADEP JAX Warehouse
DoDAAC: N65886, N39825
Inventory/Storage maintained on desktop computer excel spreadsheets

Depot Repair Cycle

Orange Park Warehouse
(off base)

NADEP Jax

Warehouse

(5)

Planner/Scheduler prepare RFI shipping document (DD Form ll49's) & sends items to NAS FISC & notify customer of units completed for appropriate delivery point.

FISC
Preserves/Packs items for DDJF shipment

DLA
Ships items on ZWT Doc ID

(4)

PC notifies Planner/Scheduler of RFI items makes a WCS 275 Transaction selling a unit and H-4 transaction for condem

(1)

Planner/Scheduler calls for items for induction from ware-house & uses WCS for Depot induction of items/processing documents & notifies production control

(2)

Production Controller (PC) inducts items into shop

(3)

Shop Repair/Make item RFI

Out Bound Shipments

Planner/Scheduler

send RFI items to FISC

DLA

DDJF Ships items on DSS ZWT transactions only. DDJF has an in-box for NADEP to pick-up copy (1) of DD1149. This procedure verifies asset shipment.

Field Activity

base / location

No DSS acceptance transactions.

Fleet Industrial Supply Center (FISC)

Preserves/Packs items for DDJF shipment. Forwards signed copy (2) of DD1149 back to NADEP.

A/F ALC DLA

location

D6 Doc ID DSS acceptance transaction.